

Protect Your Home, Family, Pets & The Environment

Avoid costly environmental cleanups.

Carefully clean and inspect the filter bowl prior to replacing the filter at the start of each heating season.

B139 Series-15: Installation Code For Oil-Burning Equipment

Annex L.1. Regular Maintenance

L.1.1. The owner or operator of the oil-burning equipment shall ensure, at least once per year, that it is maintained in accordance with Clauses L.1.2 to L.5.

Note: Maintenance should also be in accordance with the manufacturer's instructions.

If You See This:

- Rust or Corrosion
- Hole In Bottom of Can
- Rust on outside of can

If any of the defects listed above, or any other defect is found:



Install a New Epoxy-Coated Oil Filter or Filter Bowl Kit Today!



GF-1A-25B

Complete Unit

- Epoxy Coated Inside & Out For Long-Lasting Durability
- Bottom Bolt Design
- BioGasket® Standard With All Filters
- 10 Micron
- Compatible With Bio-Fuel Blends To B100!

GF-10821
Epoxy Bowl
2A-700/99



GF-10542
Epoxy Bowl
1A-25B

Replacement Bowl

- Epoxy Coated Inside & Out For Long-Lasting Durability
- Bottom Bolt Design
- Compatible With Bio-Fuel Blends To B100!
- Kit Includes Felt Element, Filter Bowl, Vent Screw, Center Bolt & All Gaskets

The Strategy

- Protect fuel delivery companies / contractors / homeowner from oil disasters
- Avoid costly oil spills and insurance premiums
- Avoid contractors and wholesalers from being sued by insurance companies and absorbing costly legal bills

Key Contractor Initiatives

- Follow B139 requirement for yearly maintenance of oil filter
- Follow B139 mandate of annual and thorough filter bowl inspection



We recommend replacement of any pre-2009 galvanized filter bowls with newer epoxy coated version introduced in 2009

Don't Risk It!

Use Only General Filters Approved Products

Use only General Filters Approved Products



This Could Have Been Avoided.

This oil leak resulted in a house being bulldozed, and the home owner filing a \$1,000,000 claim; all because the technician put in a competitor's replacement filter that pinched the gasket and created a leak.

Brand	Filter Assembly	Filter Replacement	Filter Bowl Replacement
	GFI	GF1A-25B	1A - EpoxyG (GF-10542)
	GFI	GF2A-700B	2A-EpoxyG (GF-10821)

Canadian General Filters, Inc.
 400 Midwest Road
 Toronto, ON M1P3A9
 CANADA



Canadian General Filters
 Limited